GREEN MOUNTAIN ENGINEERING, INC.

1438 South Brownell Road P.O. Box 159 Williston, VT 05495 (802) 862-5590 (Fax) 862-7598

via email May 10, 2021

Ms. Valerie Caples, Town Administrator 1 South St. PO Box 249 Bristol, VT 05443

RE:

Annual Inspection for Bristol Landfill

GME Project No. 25-014

Dear Ms. Capels;

Green Mountain Engineering, Inc. (GME) conducted the annual inspection of the landfill cap on April 6, 2021, for the Bristol Landfill site located on Pine Street in Bristol, Vermont. Enclosed, please find the Explanation of Findings and Photos from the inspection.

A summary of the issues identified during the inspection include minor soil erosion that occurred in some areas, some damage from mowing machinery, and some washouts along the northern limits. GME recommends that areas of disturbance and erosion be restored by scarifying, filling (if needed) and seeding.

If you have any questions regarding these documents, please feel free to contact our office.

Respectfully,

GREEN MOUNTAIN ENGINEERING, INC.

Bea Caver

Engineering Technician

Alan Huizenga, P.E.

President

enc. cc: Explanation of Findings Bristol Landfill Inspection April 6, 2021

Explanation of Findings Bristol Landfill Inspection Report - 2021

Green Mountain Engineering, Inc. performed the inspection for the Bristol Landfill and has recommended the following items be considered for maintenance and/or repair:

- 1. Several areas of the cap showed erosion in 2020. Most of these areas have been repaired. Photo#1-2
- 2. Some areas still show erosion that appears to be mostly from vehicular traffic. These areas can be seen in attached **Photos #1 & #2- #4** and marked up site plan. The areas shown on the marked plans are approximate, and GME recommends that all areas of erosion be scarified, filled, and reseeded to prevent erosion through the cap.
- 3. **Photo #5** shows an area where animals have burrowed into the cap. This area should be restored to prevent erosion.
- 4. The drainage swale along the north limits of the landfill cap is showing some erosion as shown in **Photo #6**. Any areas where the outer drainage swale is eroded should be restored.

Bristol Landfill Inspection Report – April 2021 Inspection Photographs



Photo #1: Erosion has been repaired, more erosion showing.



Photo #3: Erosion from vehicular traffic on south facing slope.



Photo #2: Erosion has been repaired in these areas on the south facing slope



Photo #4: Erosion from vehicular traffic along southeast slope

Bristol Landfill Inspection Report – April 2021 Inspection Photographs



Photo #5: Animal holes along southern limit.



Photo #6: Eroded area on north facing drainage swale

