



Figure 1. Side door overhang, north side. (09/10/2021)



Figure 2. North side peeling paint. (09/10/2021)



**Figure 3.** Front steps and porch. (09/10/2021)



**Figure 4.** Front steps and porch, south side. (09/10/2021)





**Figure 5.** Front steps and porch, north side. (09/10/2021)



**Figure 6.** North side of the building. (09/10/2021)



**Figure 7.** Closer view of upper roof eave deterioration. (09/10/2021)