

### **ADDENDUM #3**

**Lincoln Road Riverbank Repair  
Bristol, Vermont  
July 19, 2023**

#### **QUESTIONS AND RESPONSES:**

*Q. Looking at the scale of the wall on plan sheet XS-2 it seems to me that wall will end up being about 7.5 wide is that a correct observation?*

A. Yes, that is correct.

*Q. Will we need to divert the water to get into the bedrock to start the block wall cause that will be underwater at almost all times?*

A. The intent is that the work for the first course of the wall will be in low flow conditions, but may have some water when starting the wall. Attempts to divert flow at these sites would likely be ineffective given the setting. That being said, discharges of turbid water shall be minimized to the full extent practicable.

No other questions were received. All other conditions remain the same.

**END OF ADDENDUM #3**