

UFP Damages 2019 Oct 17 – Eagle Park, Bristol

Just past peak flow conditions at the park – 13:35



Clean-up Day #1 – 19 Oct 2019

Before:



After Clean Up Day #1 - (2 person crew, 2 hours, including chain saw) (Durand and Underwood)



Still more work to clear debris from ADA ramp and fill scour holes in ramp with Sure Pak. Second work day being planned for 10/26 or 10/27 by Bristol CC with posting to Front Porch Forum.

Platform is now cantered slightly toward the upstream corner (i.e., is no longer level, but slopes to the northeast). A kayaker (Will Perini from Starksboro) helped Randy and Kristen inspect the platform foundation by paddling underneath to inspect where the platform is bolted to the big boulders. He reported that one of the fastening brackets was severely bent and a second appeared to be pulled away from the mounting plate.

Cleanup Day #2, 26 October 2019

After Clean Up Day #2 - (5 person crew, 1.5 hours, including chain saw)
(Durand, Underwood, Henderson, Diminico, volunteer from New Haven)





Bank-side bracket




River-side bracket

Peak flow (provisional) recorded at USGS gage at Brooksville: **9,900 cfs** at 15:30, 10/17/19

Approximate: **Q10 storm**

Discharge, cubic feet per second

Most recent instantaneous value: 471 10-20-2019 10:30 EDT




Create [presentation-quality](#) / [stand-alone](#) graph. Subscribe to [WaterAlert](#)

Precipitation, total, inches

Most recent instantaneous value: 0.00 10-20-2019 10:30 EDT

Expect there was more rain in Lincoln (anecdotally)



Create [presentation-quality](#) / [stand-alone](#) graph. Subscribe to [WaterAlert](#)