

Stormwater Annual Inspection Report

version 1.14

(Submission #: HNZ-7JYY-GVQZ4, version 1)

Details

Form Alias Stormwater Annual Inspection Report
Form Started 4/23/2020 11:05 AM by Ben Cayer
Form Submitted 4/24/2020 8:32 AM by Ben Cayer
Submission # HNZ-7JYY-GVQZ4
Status Submitted
Permit # 7468-9015.T

Form Input

Permit Information

Permit Number
7468-9015.T

Permit Name
Stoney Hill Properties (f.k.a. Town of Bristol Fire Station)

Permit Location
79 West Main Street

Permit Status
Issued

1. Has ownership changed since previous authorization?
No

2. Has the amount of impervious area changed since previous authorization?
No

3. Has the project been constructed?
Yes

Maintenance Inspection Checklist

4. Are there any vegetated areas that require mowing or other maintenance?
No

5. Do catch basins need maintenance or sediment removed from sumps?
No

6. To the best of your knowledge, have there been any illicit discharges to the system (illicit discharges would include dumping of oil, gas, detergent, vehicle wash water, etc)?
No

7. Has there been any re-routing of stormwater to avoid the system?
No

8. Was any erosion noted during inspection (for example in areas of exposed soil in channels, outlets, or on pond berms)?
No

9. Was any accumulation of sediment noted in the basins, ponds, or constructed wetlands?

No

10. Is there any additional maintenance or repairs needed at this time?

No

Statement of Compliance

Inspector's Name

Ben Cayer

Title

Engineering Technician

Email

bcayer@gmeinc.biz

Phone

802-862-5590

Inspector's Mailing Address (Ignore any address validation errors that are displayed)

1438 South Brownell Road

Williston, Vermont 05495

11. Date of Inspection

3/30/2020

Please select from the dropdown below, which of these options apply.

A - MAINTAINED. Based on the noted observations, and to the best of my knowledge, this report can serve as confirmation that the stormwater system is being maintained and operated in general conformance with the approved plans and the discharge permit referenced above, and that the stormwater system is in good operating condition.

B - NOT MAINTAINED. Based on the noted observations, and to the best of my knowledge, this report can serve as notification that the stormwater system is not being maintained and operated in general conformance with the approved plans and the discharge permit referenced above, and that the stormwater system is not in good operating condition.

NOTE: If you indicated in the Permit Information section that the project has not been constructed, "C - NOT CONSTRUCTED" will already be selected.

12. Statement of Compliance

A - MAINTAINED

Attachments

Annual Inspection Report Attachments

03-30-20 Padraic Monks re. Insp. Report signed.pdf - 04/24/2020 08:22 AM

Comment

NONE PROVIDED

Attachments

Date	Attachment Name	Context	User
4/24/2020 8:22 AM	03-30-20 Padraic Monks re. Insp. Report signed.pdf	Attachment	Ben Cayer

GREEN MOUNTAIN ENGINEERING, INC.

1438 South Brownell Road
P.O. Box 159
Williston, VT 05495
(802) 862-5590 (Fax) 862-7598

.via email

March 30, 2020

Mr. Padraic Monks, Program Manager
Stormwater Management Section
VT ANR / Water Quality Division
1 National Life Drive, Main 2
Montpelier, VT 05620-3522

RE: Town of Bristol Fire Station
Authorization to Discharge Permit No. 7468-9015.T
GME Project No. 27-015

Dear Mr. Monks;


Enclosed, please find a completed Annual Inspection Report Form, as provided by the Department, for the above-mentioned project in Bristol, Vermont. Attachment No. 1 includes site photos from the inspection.

Per the "Annual Inspection and Report" criteria outlined in the Authorization to Discharge Permit, an inspection was conducted on March 30th, between the spring snow melt and June 15, 2020. The inspection evaluated the operation and maintenance and satisfactory condition of the stormwater collection, treatment and control system. The site was found to be in good overall condition with no erosion or sediment build-up in the basin.

Should you have any questions regarding this information or report, please feel free to contact me at (802) 862-5590.

Sincerely,

GREEN MOUNTAIN ENGINEERING, INC.



Benjamin P. Cayer
Engineering Technician

enc.

cc: Valerie Capels, Town Administrator w/ enc.
cc: Brett LaRose, Bristol Fire Chief w/ enc.

ANNUAL INSPECTION REPORT – March 2020
INSPECTION PHOTOGRAPHS



Photo#1: South Entrance Grass Swales



Photo #2: North Entrance Drive



Photo #3: Main Basin Overflow Outlet



Photo #3: Main Basin



Photo #4: Small Basin